

SUBJECT : Waterbags for old DG-100's with dump valve  
in the fuselage

EFFECTIVITY : DG-100 and DG-100G Ser.No. 1 - 103  
(not DG-100 ELAN)

ACCOMPLISHMENT : none, with defective bags

REASON : for this version spare bags are no more  
available

INSTRUCTIONS : Modification according to drawing F18  
Connect the new waterbag F16 (nylon fabric  
reinforced) with connector F17. The GFRP  
plate fixed to the old bag in the wingroot-  
rib must be used again.

MATERIAL : drawing F18  
2 pieces F16 waterbags  
2 pieces F17 with 2 O•rings Di = 28.2 mm  
Da = 35.2 mm  
b = 3.5 mm

Bruchsal 4, date 15.03.94

Author: Dipl.-Ing. W. Dirks



